

CONVERSÃO: POLEGADA E MILÍMETRO

Polegada	Milímetro	Polegada	Milímetro	Polegada	Milímetro	Polegada	Milímetro
1/64	0,397	21/64	8,334	41/64	16,272	61/64	24,209
1/32	0,794	11/32	8,731	21/32	16,669	31/32	24,606
3/64	1,191	23/64	9,128	43/64	17,066	63/64	25,003
1/16	1,588	3/8	9,525	11/16	17,463	1	25,400
5/64	1,984	25/64	9,922	45/64	17,859	1.1/4	31,750
3/32	2,381	13/32	10,319	23/32	18,256	1.1/2	38,100
7/64	2,778	27/64	10,716	47/64	18,653	1.3/4	44,450
1/8	3,175	7/16	11,113	3/4	19,050	2	50,800
9/64	3,572	29/64	11,509	49/64	19,447	2.1/2	63,500
5/32	3,969	15/32	11,906	25/32	19,844	3	76,200
11/64	4,366	31/64	12,303	51/64	20,241	3.1/2	88,900
3/16	4,763	1/2	12,700	13/16	20,638	4	101,600
13/64	5,159	33/64	13,097	53/64	21,034	4.1/2	114,300
7/32	5,556	17/32	13,494	27/32	21,431	5	127,000
15/64	5,953	35/64	13,891	55/64	21,828	5.1/2	139,700
1/4	6,350	9/16	14,288	7/8	22,225	6	152,400
17/64	6,747	37/64	14,684	57/64	22,622	7	177,800
9/32	7,144	19/32	15,081	29/32	23,019	8	203,200
19/64	7,541	39/64	15,478	59/64	23,416	9	228,600
5/16	7,938	5/8	15,875	15/16	23,813	10	254,000

TABELA DE ROSCAS

Polegada	Fios por Polegada	
	UNC	UNF
1/8	40	44
5/32	32	36
3/16	24	32
7/32	24	28
1/4	20	28
5/16	18	24
3/8	16	24
7/16	14	20
1/2	13	20
1/2 BSW	12	-
9/16	12	18
5/8	11	18
3/4	10	16
7/8	9	14
1	8	12

Milímetro	Passo	
	MA	MB
M 3	0,50	0,35
M 4	0,70	0,50
M 5	0,80	0,50
M 6	1,00	0,75
M 8	1,25	1,00
M 10	1,50	1,00
M 12	1,75	1,50
M 14	2,00	1,50
M 16	2,00	1,50
M 18	2,50	1,50
M 20	2,50	1,50
M 22	2,50	2,00